

Lab Coat Sizing Body Measurements

4.5 OZ Flame Resistant & Chemical Protective(FR/CP)

Point of Measurement Description	FR/CP SIZES MEN										
Size	XXS	XS	SM	MD	LG	XL	2XL	3XL	4XL	5XL	
Chest Circumference (Inches)	37	39	40	42	43	47	52	57	62	67	
Sleeve Length Regular (Inches)	32	33	33	34	35	36	38	40	42	43	
Center Back Length of Garment	34 1/2	35	35 1/2	36	37	38	39	40	41	42	

Point of Measurement Description	FR/CP SIZES WOMEN										
Size	XXS	XS	SM	MD	LG	XL	2XL	3XL	4XL	5XL	6XL
Chest Circumference (Inches)	32	34	36	38	40	43	46	50	54	58	62
Sleeve Length Regular (Inches)	31	31	32	33	33	34	35	35	36	37	38
Center Back Length of Garment	34	34 1/2	35	35 1/2	36	36 1/2	37	37 1/2	38	38 1/2	39

Fasion Seal Healthcare Lab Coats

Barrier / Fluid Resistance (Biological Materials)

Size	XXS	XS	S	M	L	XL	2XL	3XL	4XL	5XL	
Ladies' Jacket Size	2 - 4	2 - 8	10 - 12	14-16	18-20	22-24	26-28	30-32	34-36	38-40	
Men's Jacket Size	26-28	30-32	34-36	38-40	42-44	46-48	50-52	54-56	58-60	62-64	

Size	XXS	XS		S		M		L		XL		2XL		3XL		4XL	
Jacket or Dress Size	0	2	4	6	8	10	12	14	16	18	20	22/42	24/44	26/46	28/48	30/50	32/52
Chest Size	30-31	31-32	32-33	33-34	34-35	35-35	36-37	38-39	39-40	40-42	42-44	44-46	46-48	48-50	50-52	52-54	54-56
Waist Size	21-22	22-23	23-24	24-25	25-26	26-27	27-28	29-30	30-31	32-33	34-35	36-37	38-39	40-41	42-43	44-45	46-47
Hip Size	32-33	33-34	34-35	35-36	36-37	37-38	38-39	41-42	42-44	44-46	46-48	48-50	50-52	52-54	54-56	56-58	58-60